

General Safety

- Always wear safety glasses.
- Report all injuries to the instructor.
- No baggy clothing or open toed shoes.
- Give your undivided attention to the machine in which you are using.
- Keep long hair tied back.
- Only use machines when instructor is present in the room.
- Check to make sure machine is in safe working condition. For example: check to make sure all guards are in place, make sure the cord is not worn, etc.
- Only use tools for which they are intended for.
- Only use machine in which you have been instructed to use.
- Make sure machine comes to a complete stop before leaving the safety zone.
- Only one student allowed in the safety zone at all times.
- Clean-up scraps and other debris.
- Keep fingers out of the blades cutting path.
- Only use clean lumber. Free of nails, paint, and other obstructions.
- If you need help for an operation, ask for it.
- Make all adjustments when the machine is off and stopped. If you are replacing parts remember to unplug first. Example: changing bits, changing spindle, etc.
- Wait for machines to get to full speed before beginning your operation.